

				ECO #: 1	001828
I. PRODUCT IDENTIFICATION					
Chemical Trade Name (as used on label):		Chemical Family/Cla	ssification:		
Battery Electrolyte		Acid / Corrosive			
Synonyms:					
None.		Telephone:			
			ergencies, contact EnerSys'		
Manufacturer's Name/Address:			& Safety Dept. at 610-208-1996		
		Environmental, ricatu	a Safety Dept. at 010-200-1990		
EnerSys					
P.O. Box 14145		24-Hour Emergency			
2366 Bernville Road		CHEMTREC DOMES	TIC: 800-424-9300		
Reading, PA 19612-4145		CHEMTREC INTERN	ATIONAL: 703-527-3877		
II. GHS HAZARDS IDENTIFICATION					
HEALTH		ENVIRONMENTAL		PHYSICAL	
Carcinogen Category 1A					
Skin Corrosion/Irritation Category 1A					
GHS LABEL:					
HEALTH		ENVIRONMENTAL		PHYSICAL	
Hazard Statements	Precautionary State	ments (cont.)	-		
DANGER!	Rinse skin with water				
May cause cancer from inhalation of mists.	Wash contaminated cl				
Causes severe skin burns and eye damage.			p comfortable for breathing.		
Causes severe skin burns and eye uamage.	-		p connortable for breathing.		
<b>D</b>	Immediately call a poi		nal minutes Demo	- :C	
Precautionary Statements		ously with water for seve	ral minutes. Remove contact lense	s, if present and easy to	
Obtain special instructions before use.	do. Continue rinsing.				
Do not handle until all safety precautions have been read					
and understood.					
Do not breath dusts or mists.					
Wash thoroughly after handling.					
Wear protective gloves/protective clothing, eye protection					
and face protection.					
If exposed or concerned: Get medical advice/attention.					
If swallowed: Rinse mouth. Do NOT induce vomiting.					
If on skin (or hair): Take off immediately all contaminated					
clothing					
III. COMPOSITION / INFORMATION ON INGREDIENTS					
Components		Approximate % by			
	CAS Number				
Compositing	CAS Number				
-	CAS Number	Wt.			
- Inorganic Lead Compound:		Wt.			
Inorganic Lead Compound: Sulfuric Acid	CAS Number 7664-93-9	<b>Wt.</b> 30 - 40			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O)		Wt.			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O)		<b>Wt.</b> 30 - 40			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES		<b>Wt.</b> 30 - 40			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES	7664-93-9	<b>Wt.</b> 30 - 40 60 - 70			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff	7664-93-9	<b>Wt.</b> 30 - 40 60 - 70			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff	7664-93-9 ficult, give oxygen. Consu	Wt.           30 - 40           60 - 70           It a physician.	use permanent injury or death:		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir	7664-93-9 ficult, give oxygen. Consu	Wt.           30 - 40           60 - 70           It a physician.	use permanent injury or death;		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician.	7664-93-9 ficult, give oxygen. Consu	Wt.           30 - 40           60 - 70           It a physician.	use permanent injury or death;		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin:	7664-93-9 ficult, give oxygen. Consu	Wt.         30 - 40       60 - 70         It a physician.       1000000000000000000000000000000000000			
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir	7664-93-9 ficult, give oxygen. Consu	Wt.         30 - 40         60 - 70	cluding shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co	7664-93-9 ficult, give oxygen. Consu	Wt.         30 - 40         60 - 70	cluding shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor	Wt.         30 - 40         60 - 70	cluding shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor	Wt.         30 - 40         60 - 70	cluding shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lu nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor	Wt.         30 - 40         60 - 70	cluding shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits:	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits:	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures:	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits:	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash or Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits:	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards:	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas.	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eyes: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lur nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing.		
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures:	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the luu nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear pides and other organic ma	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eyes: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the luu nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: uses acid to splatter. Wear pides and other organic ma	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures:	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate nut	Wt.         30 - 40         60 - 70         It a physician.         ngs may occur and can c         d clothing completely, in         physician.         LEL = N/A         full-cover sulfuric acid r         terials. Reacts with most         culite. Do not use combotic	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 min If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures: Stop flow of material, contain/absorb small spills wit	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate nut	Wt.         30 - 40         60 - 70         It a physician.         ngs may occur and can c         d clothing completely, in         physician.         LEL = N/A         full-cover sulfuric acid r         terials. Reacts with most         culite. Do not use combotic	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash or Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures: Stop flow of material, contain/absorb small spills wit neutralize spilled electrolyte with soda ash, sodium b allow discharge of unneutralized acid to sewer.	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate nut	Wt.         30 - 40         60 - 70         It a physician.         ngs may occur and can c         d clothing completely, in         physician.         LEL = N/A         full-cover sulfuric acid r         terials. Reacts with most         culite. Do not use combotic	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures: Stop flow of material, contain/absorb small spills wit neutralize spilled electrolyte with soda ash, sodium b allow discharge of unneutralized acid to sewer. VI. HANDLING AND STORAGE	7664-93-9 ficult, give oxygen. Consu ng or aspiration into the lui nutes; remove contaminate nut	Wt.         30 - 40         60 - 70         It a physician.         ngs may occur and can c         d clothing completely, in         physician.         LEL = N/A         full-cover sulfuric acid r         terials. Reacts with most         culite. Do not use combotic	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash co Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures: Stop flow of material, contain/absorb small spills wit neutralize spilled electrolyte with soda ash, sodium b allow discharge of unneutralized acid to sewer. VII. HANDLING AND STORAGE Handling:	7664-93-9 ficult, give oxygen. Consul ng or aspiration into the lui nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: . uses acid to splatter. Wear bides and other organic ma th dry sand, earth or vermi bicarbonate, lime, etc. Wea	Wt.         30 - 40         60 - 70	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu boots, gloves and face shield. Do t	mable	
Inorganic Lead Compound: Sulfuric Acid Water (H <sub>2</sub> O) IV. FIRST-AID MEASURES Inhalation: Remove to fresh air immediately. If breathing is diff Ingestion: Give large quantities of water; do not induce vomitir consult a physician. Skin: Flush with large amounts of water for at least 15 mir If symptoms persist, seek medical attention. Wash or Eves: Flush immediately with large amounts of water for a V. FIRE-FIGHTING MEASURES Flash Point: N/A Extinguishing Media: CO <sub>2</sub> ; foam; dry chemical; water; water fog. Special Fire Fighting Procedures: Water applied to sulfuric acid generates heat and cau Unusual Fire and Explosion Hazards: Reacts violently with metals, nitrates, chlorates, carb hydrogen gas. VI. ACCIDENTAL RELEASE MEASURES Spill or Leak Procedures: Stop flow of material, contain/absorb small spills wit neutralize spilled electrolyte with soda ash, sodium b allow discharge of unneutralized acid to sewer.	7664-93-9  ficult, give oxygen. Consu ag or aspiration into the lui nutes; remove contaminate ontaminated clothing befor least 15 minutes; consult Flammable Limits: . uses acid to splatter. Wear bides and other organic ma th dry sand, earth or vermi bicarbonate, lime, etc. Wea andling areas should be equ	Wt.         30 - 40         60 - 70         It a physician.         ngs may occur and can c         d clothing completely, in         re reuse. Discard contamplysician.         LEL = N/A         full-cover sulfuric acid r         terials. Reacts with most         culite. Do not use combinary acid-resistant clothing,         uipped with proper contage	cluding shoes. inated shoes. UEL = N/A esistant clothing. metals to yield explosive and flam stible materials. If possible, carefu boots, gloves and face shield. Do t	mable	

Storage:						
Store in cool, dry, well-ventilated areas with impervious surfaces and Store and handle only in areas with adequate water supply and spill co		•	• •			
VIII. EXPOSURE CONTROLS/PERSONAL PROTECTION	inton. Avoid damage t	o containers. Reep awa	ty from metallic objects			
Exposure Limits (mg/m <sup>3</sup> ) Note: N.E.= Not Established						
INGREDIENTS OSHA PEL	ACGIH	US NIOSH	Quebec PEV	Ontario OEL	EU OEL	
Electrolyte (Sulfuric Acid) 1	0.2	1	1	0.2	0.05 (a)	
NOTES:						
(a) Thoracic fraction Engineering Controls (Ventilation):						
Store and handle in well-ventilated area. If mechanical	ventilation is used, con	mponents must be acid-	resistant.			
Respiratory Protection (NIOSH/MSHA approved):	,	1				
None required under normal conditions. When concern	trations of sulfuric aci	d mist are known to exc	eed the PEL, use NIOS	H or MSHA-approved		
respiratory protection.						
Skin Protection: Use rubber or plastic acid-resistant gloves with elbow-	length gauntlet acid-re	sistant apron clothing	and boots			
Eve Protection:	iengui gaunnet, aciu-re	sistant apron, crothing a	and boots.			
Use chemical goggles or face shield.						
Other Protection:						
In areas where sulfuric acid is handled in concentration	-			-		
with unlimited water supply. Acid-resistant apron. Und	-		ar acid-resistant clothin	ig and boots.		
Face shield recommended when adding water or electronic at a ND CHEMICAL PROPERTIES	olyte to batteries, wash	hands after handling.				
IX. PHYSICAL AND CHEMICAL PROPERTIES Properties Listed Below are for Electrolyte:						
Boiling Point:	203 - 240° F	Specific Gravity (H	20 = 1):	1.215 to 1.350		
Melting Point:	N/A	Vapor Pressure (m		10		
Solubility in Water:	100%	Vapor Density (AII		Greater than 1		
Evaporation Rate: (Butyl Acetate = 1)	Less than 1	% Volatile by Weig	ght:	N/A		
pH		Flash Point:	• • •	N/A		
LEL (Lower Explosive Limit)	N/A	UEL (Upper Explo		N/A		
Appearance and Odor: X. STABILITY AND REACTIVITY	Electrolyte is a clear	inquid with a sharp, per	etrating, pungent odor.			
Stability:     Stability:       Stability:     Stability:						
This product is stable under normal conditions at ambient temper	rature.					
Conditions To Avoid: Contact with organic materials, combustibles,	strong reducing agents	, metals, strong oxidize	rs, water.			
Incompatibility: (Materials to avoid)						
Contact with combustibles and organic materials may o	-	-		-		
metals, sulfur trioxide gas, strong oxidizers and water.	Contact with metals n	ay produce toxic sulfu	dioxide fumes and mag	y release flammable		
hydrogen gas. Hazardous Decomposition Products:						
<u>Sulfuric Acid:</u> Sulfur trioxide, carbon monoxide, sulfu	ric acid mist, sulfur die	oxide, and hydrogen sul	lfide.			
Hazardous Polymerization:		· · ·				
Will not occur.						
XI. TOXICOLOGICAL INFORMATION						
Routes of Entry: Harmful by all routes of entry.						
Inhalation:						
Breathing of sulfuric acid vapors or mists may cause se	evere respiratory irritat	ion.				
Ingestion:						
May cause severe irritation of mouth, throat, esophagu	s and stomach.					
Skin Contact:						
Severe irritation, burns and ulceration. Eve Contact:						
Severe irritation, burns, cornea damage, and blindness						
Effects of Overexposure - Acute:						
Severe skin irritation, damage to cornea, upper respirat	ory irritation.					
Effects of Overexposure - Chronic: Possible erosion of tooth enamel inflammation of possible	a throat and hearshirt	tubec				
Possible erosion of tooth enamel, inflammation of nose Carcinogenicity:	, anoat and bronchial	11005.				
The International Agency for Research on Cancer (IAF	RC) has classified "stro	ng inorganic acid mist	containing sulfuric acid	" as a		
Group 1 carcinogen, a substance that is carcinogenic to	humans. This classifi	cation does not apply to	o liquid forms of sulfuri	c acid or sulfuric		
acid solutions contained within a battery. Inorganic ac	id mist (sulfuric acid m	nist) is not generated un	der normal use of this p	product. Misuse of the		
product, such as overcharging, may result in the genera	product, such as overcharging, may result in the generation of sulfuric acid mist.					
Drop 65, Waming, Culturin Arid Mirelis Income of	State of California (	0000 000000				
Prop 65: Warning: Sulfuric Acid Mist is known to the Medical Conditions Generally Aggravated by Exposure:	State of California to c	ause cancer.				
Overexposure to sulfuric acid mist may cause lung dan	nage and aggravate pul	monary conditions. Co	ntact of sulfuric acid wi	ith skin may aggravate		
diseases such as eczema and contact dermatitis. Lead		-				
Acute Toxicity:						
Inhalation LD50:						
LC50 rat: 375 mg/m <sup>3</sup> ; LC50: guinea pig: 510 mg/m <sup>3</sup>						
<b>Oral LD50:</b> rat: 2140 mg/kg						
rat: 2140 mg/kg Additional Health Data:						
Most inhalation problems can be avoided by adequate	precautions such as ver	ntilation and respiratory	protection covered in S	Section 8.		
Follow good personal hygiene to avoid inhalation and	-		-			
worksite. Keep contaminated clothing out of non-conta	-					
tobacco and cosmetics to non-contaminated areas. Wo	rk clothes and work eq	uipment used in contam	ninated areas must rema	in in designated areas and		
never taken home or laundered with personal non-cont	aminated clothing. Thi	s product is intended fo	r industrial use only and	d should be isolated from		
children and their environment.						

	GICAL INFORMATION			
Environment				
	Sulfuric acid can lower water and soil pH cau	sing acidic conditions; reacts with calc	ium and magnesium to form sulfate salts.	
Environment	tal Toxicity: Aquatic Toxicity:			
		h (Brachydanio rerio): 82 mg/L		
Additional In		ish (Cyprinus carpio): 22 mg/L		
Auunonai II	• No known effects on stratospheric ozone de	pletion.		
	Volatile organic compounds: 0% (by Volum	-		
	· Water Endangering Class (WGK): NA			
	SAL CONSIDERATIONS (UNITED STAT			
	zed slurry into sealed containers and handle as			
	and testing, should be managed in accordance	with approved local, state and federal	requirements. Consult state environmental	
agency and/or Following loc:		ations applicable to end-of-life charac	teristics will be the responsibility of the end-user.	
	SPORT INFORMATION	ations applicable to end-or-life charac	consider will be the responsionity of the end-user.	
U.S. DOT:				
	The shipping information is as follows:			
	Proper Shipping Name: Ba	attery Fluid, Acid	Packing Group: II	
	Hazardous Class: 8 UN Identification: UN279		Label/Placard Required: Corrosive	
	Contact your EnerSys representative for addit		fication of batteries	
	Contact your Energy's representative for addit	nonai mormanon regarang no enassi		
	Reference 49 CFR packing instructions: 173.	154 or 173.202 or 173.242		
IATA Dange	rous Goods Regulations DGR:			
	The shipping information is as follows:	ottom: Thrid A -14	Desking Cream, H	
	Proper Shipping Name: Ba Hazardous Class: 8	attery Fillid, Acid	Packing Group: II Label/Placard Required: Corrosive	
	UN Identification: UN279	96	Labert facale Required. Conosive	
	Reference IATA packing instructions Y840 o	r 851 or 855		
IMDG:				
	The shipping information is as follows:			
	Proper Shipping Name: Ba Hazardous Class: 8	attery Fluid, Acid	Packing Group: II	
	UN Identification: UN279	96	Label/Placard Required: Corrosive	
	Reference IMDG Packing instructions P001			
	ATORY INFORMATION			
UNITED STA				
EPA SARA T	EPCRA Extremely Hazardous Substances (EHS	· · ·		
Section 302 E				
	• • • • • • • • • • • • • • • • • • •		reshold Planning Quantity (TPQ) of 1 000 lbs	
	Sulfuric acid is a listed "Extremely Hazardous	s Substance" under EPCRA, with a Th	reshold Planning Quantity (TPQ) of 1,000 lbs. resent at one site (40 CFR 370.10). For more information consult	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p	reshold Planning Quantity (TPQ) of 1,000 lbs. resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information.	
Section 304 C	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p	resent at one site (40 CFR 370.10). For more information consult	
Section 304 C	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information.	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information.	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit 12 Hazard Categorization:	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and tte and local reportable quantities for spilled sulfuric acid may vary.	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is read	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit 12 Hazard Categorization:	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is rea- present in quantities of 10,000 lbs or more. For	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is	
	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is requires present in quantities of 10,000 lbs or more. For fication:	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% su EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC. <u>Toxic Chemical</u>	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports:	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC	Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u>	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u>	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u>	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is required present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year.	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufacturing	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is rea- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year. TSCA Section 8b – Inventory Status: All chemical	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment wer exempt or listed on the TSCA Inventory.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is required present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year.	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment wer exempt or listed on the TSCA Inventory.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is rec present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 8b – Inventory Status: All chemical TSCA Section 12b (40 CFR Part 707.60(b)) I	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this you import this product, the following ;	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation:	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact you ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this you import this product, the following si uply with all applicable rules or orders	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product.	
Section 311/3	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact you ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this you import this product, the following si uply with all applicable rules or orders	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and the and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation:	
Section 311/3 Supplier Noti TSCA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact you ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this you import this product, the following : mply with all applicable rules or orders rder under TSCA.	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in	
Section 311/3 Supplier Noti	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required in 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is required in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com violation of TSCA or any applicable rule or of Spilled sulfuric acid is characterized as a haza	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this you import this product, the following : uply with all applicable rules or orders rder under TSCA.	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in mber D002 (corrosivity).	
Section 311/3 Supplier Noti TSCA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is required in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufactor of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com violation of TSCA or any applicable rule or of Spilled sulfuric acid is characterized as a haza EnerSys supports preventative actions concer-	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this rou import this product, the following : uply with all applicable rules or orders rder under TSCA.	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in mber D002 (corrosivity). e due to emissions of CFC's and other ozone depleting	
Section 311/3 Supplier Noti TSCA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For ification: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 8b – Inventory Status: All chemical TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com- violation of TSCA or any applicable rule or or Spilled sulfuric acid is characterized as a haza EnerSys supports preventative actions concer- chemicals (ODC's), defined by the USEPA as	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this rou import this product, the following : uply with all applicable rules or orders rder under TSCA. urdous waste; EPA hazardous waste nu ning ozone depletion in the atmospher : Class I substances. Pursuant to Secti	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment er exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in <u>mber D002 (corrosivity).</u> e due to emissions of CFC's and other ozone depleting on 611of the Clean Air Act Amendments (CAAA)	
Section 311/3 Supplier Noti TSCA: RCRA: CAA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com violation of TSCA or any applicable rule or o Spilled sulfuric acid is characterized as a haza EnerSys supports preventative actions concer- chemicals (ODC's), defined by the USEPA as of 1990, finalized on January 19, 1993, EnerS	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this rou import this product, the following : uply with all applicable rules or orders rder under TSCA. urdous waste; EPA hazardous waste nu ning ozone depletion in the atmospher : Class I substances. Pursuant to Secti	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment her exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in mber D002 (corrosivity). e due to emissions of CFC's and other ozone depleting	
Section 311/3 Supplier Noti TSCA: RCRA: CAA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) 1 TSCA Section 13 (40 CFR Part 707.60(b)) 1 TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com violation of TSCA or any applicable rule or o Spilled sulfuric acid is characterized as a haza EnerSys supports preventative actions concer- chemicals (ODC's), defined by the USEPA as of 1990, finalized on January 19, 1993, EnerS <b>ULATIONS (US):</b>	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact yo ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this rou import this product, the following : uply with all applicable rules or orders rder under TSCA. urdous waste; EPA hazardous waste nu ning ozone depletion in the atmospher : Class I substances. Pursuant to Secti	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment er exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in <u>mber D002 (corrosivity).</u> e due to emissions of CFC's and other ozone depleting on 611of the Clean Air Act Amendments (CAAA)	
Section 311/3 Supplier Noti TSCA: RCRA: CAA:	Sulfuric acid is a listed "Extremely Hazardous EPCRA Section 302 notification is required it 40 CFR Part 355. The quantity of sulfuric acid ERCLA Hazardous Substances: Reportable Quantity (RQ) for spilled 100% st EPCRA (Emergency Planning and Communit 12 Hazard Categorization: EPCRA Section 312 Tier Two reporting is re- present in quantities of 10,000 lbs or more. For fication: This product contains toxic chemicals, which If you are a manufacturing facility under SIC <u>Toxic Chemical</u> Sulfuric Acid If you distribute this product to other manufac of each calendar year. TSCA Section 12b (40 CFR Part 707.60(b)) I TSCA Section 13 (40 CFR Part 707.20): If y All chemical substances in this shipment com violation of TSCA or any applicable rule or o Spilled sulfuric acid is characterized as a haza EnerSys supports preventative actions concer- chemicals (ODC's), defined by the USEPA as of 1990, finalized on January 19, 1993, EnerS	s Substance" under EPCRA, with a Th f 1000 lbs or more of sulfuric acid is p d will vary by battery type. Contact you ulfuric acid under CERCLA (Superfur ty Right to Know Act) is 1,000 lbs. Sta quired for non-automotive batteries if or more information consult 40 CFR 3 may be reportable under EPCRA Sect codes 20 through 39, the following in <u>CAS Number</u> 7664-93-9 cturers in SIC Codes 20 through 39, th micals comprising this product are eith No notice of export is required for this rou import this product, the following : uply with all applicable rules or orders rder under TSCA. urdous waste; EPA hazardous waste nu ning ozone depletion in the atmospher class I substances. Pursuant to Secti Sys established a policy to eliminate th	resent at one site (40 CFR 370.10). For more information consult ur EnerSys representative for additional information. d) and te and local reportable quantities for spilled sulfuric acid may vary. sulfuric acid is present in quantities of 500 lbs or more and/or if lead is 70.10 and 40 CFR 370.40. ion 313 Toxic Chemical Release Inventory (Form R) requirements. formation is provided to enable you to complete the required reports: <u>Approximate % by Wt.</u> 30 - 40 is information must be provided with the first shipment er exempt or listed on the TSCA Inventory. product. statement must be included on the invoice or entry documentation: under TSCA. This chemical substance is not offered for entry in <u>mber D002 (corrosivity).</u> e due to emissions of CFC's and other ozone depleting on 611of the Clean Air Act Amendments (CAAA)	

INTERNATIONAL REGULATIONS:	
Distribution into Quebec to follow Can	adian Controlled Product Regulations (CPR) 24(1) and 24(2).
	-
Distribution into the EU to follow appli	icable Directives to the Use, Import/Export of the product as-sold.
XVI. OTHER INFORMATION	
Revised: AB (04-25-17)	
NFPA Hazard Rating for Sulfuric Acid:	
Flammability (Red) $= 0$	Reactivity (Yellow) = 2
Health (Blue) $= 3$	Sulfuric acid is water-reactive if concentrated
DISCLAIMER	
This Safety Data Sheet is created by the manufacturer	to comply with the requirements of 29 CFR 1910.1200. To the extent allowed by law,
the manufacturer hereby expressly disclaims any liabili	ity to any third party, including users of this product, including, but not limited to, consequential or
other damages, arising out of the use of, or reliance on	, this Safety Data Sheet.